

ENTRETIEN POMPE À CHALEUR AIRPAC

56670 Riantec | Morbihan (56)

ref : 59795



Fiche en ligne



Artipac
06.82.71.70.82

Chantier réalisé en : 2026

Depuis juillet 2020, la maintenance des pompes à chaleur est obligatoire :

<https://www.legifrance.gouv.fr/jorf/id/JORFTEXT000...>

Intervention à Riantec, proche Lorient dans le Morbihan (56).

Un entretien régulier d'une pompe à chaleur permet d'allonger sa durée de vie, de prévenir les pannes éventuelles et les fuites du fluide frigorigène.

En l'espèce, entretien d'une Sanyo. Les points de contrôle nécessaires pour la maintenance annuelle de votre pompe à chaleur :

- Vérification des cartes situées dans l'unité extérieure,
- Nettoyage des filtres principaux,
- Vérification de la pression du vase d'expansion,
- Contrôle de performance,
- Vérification de l'étanchéité du circuit frigorigène,
- Réglages éventuels,
- Serrages des connexions électriques,
- Test de turbidité (mesure de la qualité de l'eau afin de déterminer si un desembouage est nécessaire).
- Changement préventif des pièces montrant des signes d'usures avancées afin de réduire un risque de panne. Exemple cosse transfo.

Since July 2020, maintenance of heat pumps has been mandatory:

<https://www.legifrance.gouv.fr/jorf/id/JORFTEXT000...>

Intervention in Languidic, between Lorient and Locminé in Morbihan (56). Regular maintenance of a heat pump extends its lifespan and prevents possible breakdowns and refrigerant leaks.



RÉSEAU
proéco-énergies

reseau-proeco-energies.fr
Un réseau d'entreprises indépendantes & solidaires

In this case, maintenance of a Sanyo. The necessary checkpoints for the annual maintenance of your heat pump:

- Checking the cards located in the outdoor unit,
- Cleaning the main filters,
- Checking the pressure of the expansion tank,
- Performance control,
- Checking the tightness of the refrigeration circuit,
- Possible settings,
- Tightening of electrical connections,
- Turbidity test (measurement of water quality to determine if desludge removal is necessary).
- Preventive change of parts showing signs of advanced wear in order to reduce the risk of breakdown.



(5/5 pour 114 avis)

Artipac

6 rue de la revolution 56700

06.82.71.70.82

<https://www.artipac.fr>

artipac@free.fr



RÉSEAU
proéco-énergies

reseau-proeco-energies.fr
Un réseau d'entreprises indépendantes & solidaires